



Service update

oktober 2008

Aerials | Dishes | Receivers | Headends | Multi switches | Amplifiers | Outlets | Home accessories | Fibre cabinets | Enclosures

Software update

TDH Manager ændringer fra version 1.03 til version 2.0

Nyt: Tilføjet understøttelse af firmware opgradering til TDH780. TDH780 og TDH778 genkendes nu i preconfiguration menu.

TDH Manager changes from version 1.03 to version 2.0

New: Added support for firmware upgrade of TDH780. TDH780 and TDH778 are now detected by the preconfiguration menu.

TRIAX Service Update is Triax A/S' internal service info.

Service Update is our means to inform you about product defects, serial defects, solutions and useful hints.

Service Update is distributed electronically via e-mail once a month or when required to relevant persons at Triax.

If you wish to receive Service Update or if you have comments or other contributions, you are welcome to contact me on jra@triax.dk or +45 7682 2273

